


2A42.07.040C6

YAMETAJ

③ Концы провода поз.2
развести. Припой зачистить
заподлицо со сд.ед. поз.1



SQUIB FIRING PIN

Assembly Drawing

Scale 5:1. Mass: 0.003

- (1) 1. Refer to GOST 23587-79 for technical requirements to electric wiring.
2. Test insulation for breakdown by voltage of 500 V 50 Hz AC for one minute.
3. Insulation resistance should not be less than 20 megohms at voltage of 500 V under normal climatic conditions.
4. Solder with solder ПОС 40, GOST 21931-76, with flux ПИ-120, ГС-40-406-73, ГСТ-92-1190-78, and coat with varnish ГВ-95, GOST 8018-70.
5. Stamp K on the lot tag

(2)

Designation	A, mm	
	rated	lim.dev.
2A42.07.040	70	±2
2A42.07.040-01	50	
2A42.07.040-02	40	

- (3) Spread the ends of wire Ref. No. 2. Dress solder flush with assembly unit, Ref. No. 1

Обозначение	A, мм	
	НОМИН.	Предупка
2A42.07.040	70	±2
-01	50	
-02	40	

FINAL DRG. FOR MFR. AT OFT

DATE 15/2/93

UP-DATED

CHECKED

F/M-PROJ

SCT. Копия Верно 10.02.93

DGM / PROJ

15.02.93

5	544Т-84	Всун	180889
---	---------	------	--------

2A42

2A42.07.040C6

SQUIB FIRING PIN

Пиробоек
ASSEMBLY DRAWING

Сборочный чертёж

Лист	Масса	Масштаб
2/3	0,003	5:1
Лист	Листов 1	