

ANNEXURE A

**LIST OF ESSENTIAL MACHINES FOR MANUFACTURING OF THE
SUBJECT ASSEMBLY**

1. LATHE (OR) CNC TURNING CENTRE
2. MILLING MACHINE (OR) CNC VMC
3. SHAPING MACHINE (OR) BROACHING MACHINE
4. HEAT TREATMENT FACILITY
5. OXIDATION BATH