QUALITY MONITORING INSTRUCTION FOR INSPECTION

Issue No: 01 Rev No:

Date of Issue 16/10/2023

C-5096 (PAWL)

OFT/MI/30 mm/ C 5096.

Rev.No Amendment Date

MATERIAL SPECIFICATION : Steel 30XPA OCT-3-98-80.

MATERIAL FOR INDIA

: BS:970 Pt.1 1983 Gde 817 M40 IN 'Z' CONDITION

CONDITION OF SUPPLY : FULL FINISHED WITH FIRM'S MATERIAL.

END USE

: 30 mm CANNON.

INSPECTION CHECK TO BE CARRIED OUT

SL NO	CHARACTERISTICS			SPECIFIC	ATION	1 / F	REQUIREMENT	SAMPLE SIZE
1.	Visual	The Component shall be smooth and as free as possible from defects, such as grooves, seams, tears, rust, scale, scratches, pits, die-marks and any other harmful defects.						
2.	Dimension	100%	6 Dii	mension check	as per	dra	wing.	
3.	Chemical Composition (%)	(As p C Si Mn Cr B	er S = = = = = 70 F = =	0.28-0.33 0.17-0.37 0.50-0.80 1.00-1.30 0.001-0.0045 1.00-1.40 1.00-1.40 1.30-1.70 0.1-0.35	5160-7 Ni S P Cu	= = = = = 40 = =	0.25-0.50 0.025(Max) / 0.025(Max) / 0.20 (Max)	One Sample Per Heat

4.	Mechanical Properties	STEEL 30XPA OCT-3-98-80 Tensile Strength = 160 Kgf/mm² (Min) Yield Strength = 130 Kgf/mm² (Min) Elongation = 9% (Min) Reduction of area = 40% (Min) Impact = 5 Kgfm/cm² (Min) BS:970 Pt1-1983 Gde 817 M40 IN 'Z' CONDITION Tensile Strength 1550 N/mm² (Min) 0.2% Proof Stress 1235 N/mm² (Min) % Elongation 5% (Min) Izod Impact 8 ft.lb (Min)	One sample Per Heat.		
5.	Hardness	(Permissible variations in value as per specification standard)			
6.	Protective Finish	43.5-51.5 HRC (As per drawing)	100%		
		As per specification in the drawing.	100%		
7.	Packing	The Packing of the Material shall be done in such a manner to avoid corrosion and damage in handling and transit.			
8.	Marking	Each Packing shall be legibly marked with manufacturer's identity, Qty, Heat No, OFT Supply order No etc.,	Each Consignment		

P.MURUGESAN HoS / QCM, CHECKED BY

U.MANGALASAMY HoS/STD.CELL

PREPARED BY

M.GIRISH KUMAR REDDY, WM(QCM)

> SUKESH GEHLAUT, Jt.GM (QCM) APPROVED

Note:

- The Raw material / component to be tested by the firm on selection of the sample by the firm itself for chemical composition and mechanical properties in NABL accredited approved Lab as per Table 'A'.
- 2. The Firm has to check for the dimensions, visual defects, packing and marking as per Table 'A'. After completion of tests as per Note-1 as above, the Firm has to submit the following documents to OFT.
 - The Raw material certificate from the original manufacturer, Heat number, and quantity purchased and number of bars is to be mentioned in the inspection letter to OFT.
 - II. The Chemical and Mechanical test certificates from NABL accredited approved lab as per Table 'A'.
 - III. Dimensional reports including visual as per Table 'A'.
 - IV. Guarantee / Warrantee certificate of supplier against the supply.
- All the above Documents mentioned at Note No.2 above are to be forwarded to ED/OFT along with supply.
- 4. OFT shall verify all the documents as above and accord clearance to the firm for dispatch of the material to OFT if all documents are in order.
- 5. OFT/Trichy shall verify all the parameters as per Table 'A' and after satisfactory results, the material will be accepted /cleared accordingly.
- 6. Material has to be replaced 100% by the firm in case of non conformity to specification as per Table-A, during inspection at OFT, Trichy.

VERIFICATION OF INSPECTION DOCUMENTS

SL_NO	INSPECTION DOCUMENTS					
1	The Raw material original Manufacturer's certificate, Details of Heat Number, Quantity purchased and number of Bars etc.,					
2	The Chemical and Mechanical test certificates from NABL accredited approved Lab.					
3	Dimension report including visual.					
4	Packing slip details.					

P.MURUGESAN HoS/QCM

CHECKED

U.MANGALASAMY HoS/STD.CELL PREPARED

M.GIRISH KUMAR REDDY WM/QCM

> SUKESH GEHLAUT Jt.GM(QCM) (APPROVED)