

ANNEXURE A

**LIST OF ESSENTIAL MACHINES FOR MANUFACTURING OF
THE SUBJECT ASSEMBLY**

1. INTERNAL DIA & EXTERNAL DIA GRINDING MACHINES
2. MILLING MACHINE AND CNC VMC (OR) CNC HMC
3. HEAT TREATMENT & CARBURRISING FACILITY
4. OXIDATION BATH & ZINC PLATING BATH
5. LATHE (OR) CNC TURNING CENTRE