

CHANGE SHEET No.295	DRAWING CHANGE SHEET			AFFECTED DRG. NO. ADRDE/1453(b)
DATED 26/04/2021	DRAWING TITLE: RIP CORD HANDLE RIP CORD ASSEMBLY FOR JAGUAR A/C			NEW DRG. NO. ADRDE/1453(c) SHEET 1 OF 1
Sl. No.	SHEET NO./ LOCATION	EXISTING	AMENDED	REASON
1.	Sheet No. 02 of 23 A-1	Material:- martensitic stainless steel tube 8±0.1mm O.D wall thickness 1.25±0.05mm as per SPEN. AISI:403	Material:- Austenitic stainless steel tube 8±0.1mm OD wall thickness 1.25±0.05mm as per SPECN. IS:6603-2001	OPF (K) vide letter No. CF-1736/Specn/T dated 23 Dec 2020 and 13 Feb 2021 requested to change the material citing the reason of non-availability of specified material. The suggested material has better corrosive resistance and suitable for subject rip cord handle.
PREPARED BY <i>Kamal</i> (KAMAL S NIKHURPA Sc 'C')		APPROVED BY <i>Sudhakar Prasad</i> 27/04/21 (SUDHAKAR PRASAD Sc 'E')		VETTED BY <i>Abhishek</i> 19/06/2021 RCMA (K) (Alok Kumar) Sc-B
AERIAL DELIVERY RESEARCH AND DEVELOPMENT ESTABLISHMENT MINISTRY OF DEFENCE AGRA CANTT				As discussed with ADDI drawing No. ADRDE/ 1453(b) & ADRDE/ 1453(c) are same & indicated accordingly drawing No.