


10-10-111111

Rz 80,
V (V)

50.610.150



1). * Dimension is given for reference.

2) Coating Cadmium plated, 9 microns thick, chromitized.



AP11-01-01

COVER

SNO	SHT	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.84
EDT, CHKO		D.K. JAIN		18.12.84
F/M, DC.		S.R. NARAYAN		19.12.84
DIV. OFFR		A.K. KUNDU		30.1.85
		NAME	SIGN	DATE


Sheet 5 0.5 GOST 19904-74
II-Br 08K17 GOST 9045-70.

SHEET	WEIGHT	SCALE.
50009		2:1
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

AP11-01-02

Rz800/ (✓)

Y3 610.130



* Dimension is given for reference.

Coating: Cadmium plated, 9 microns thick, chromatzied.



AP11-01-02

SNO	SHY	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.8
EDT,CHKD		D.K. JAIN		18.12.8
F/M,DC.		S.R. NAIR		19.12.8
DIV OFFER		A.K.K. SUDU		30.12.8


BODY

Sheet 50.5 GOST 19904-74
II Bc OKKП GOST9045-70


SHEET	WEIGHT	SCALE
5	0.012	2:1
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

3K11.044

3417 N2 33444



Sides A and B should be fused



3K11.044

BAG

SNOSHT	DOC NO	SIGN	DATE
DRAWN	BHUSHAN		17.12.84
EDT,CHKD	B.K. SAIR		18.12.84
F/M,DC	S.R. NAIR		19.12.84
DIV.OFFR	A.K. KUNDU		3.01.85
	NAME	SIGN	DATE

Polyethylene film, C, 0,1
grade-1, GOST 10354-73.

SHEET	WEIGHT	SCALE
6	1,32	1:2
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

PH10.00039T

70 CM ₁₀ (±1,5)		65 CM ₁₀ (±1,5)
PH-10 ЗИП №1		
Description	No	
② Прессоразъемник СП-10,		
② ЗОВ ТУ16-522-001-76	2	
Fuse СП-15,		
ЗОВ ТУ16-522-001-76	2	
Inspector _____		

- 1). Print using tape 03-8 GOST3489-10-71 and for inscription PH-10 ЗИП No.1" use type 63-16, GOST 3489-7-11
- 2). Manufacturing of lable by photocopying method is allowed



PH10.00039T

SNO	SHT	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.84
EDT,CHKD		D K JAIN	<i>[Signature]</i>	18.12.84
F/M,DC		S-R NAIR	<i>[Signature]</i>	19.12.84
DIV.OFFR		A.R.KUNDU	<i>[Signature]</i>	3.01.85
		NAME	SIGN	DATE

LABLE

Paper No 1 A of machine finish
grade 1 GOST 9095-73.

SHEET	WEIGHT	SCALE.
5	0052	1:1
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

PH-10
SPARE PARTS AND TOOLS
No.1
STOWAGE
Y.260.000

CONTENTS OF ALBUM No. 123


CONVENTIONAL INDEX : 84/0848711-03-55-40007

Sl. No.	DRAWINGS ASSEMBLIES ITEM Nos.	DESCRIPTION OF DOCUMENTS	DRAWING Nos. (PROCESS CHART	Qty of shts.	LATEST AMENDMENT NO.	REMARKS
1	2	3	4	5	6	7
1	Album of drawings for stowage of spare parts, tools and accessories No 1 Y 260,000	Title sheet	Y 260 000	1		
2		Parts list	Y 260 000	1		
3		Assy-drawing	Sheet 1 Y 260 000CB	1		
4		Parts list	Y3 987 010	2		
			Sheet 1 Sheet 2			
5		Assy-drawing	Y3 987.010CB	1		
6		Drawing	PH10 00033T	1		
7		Drawing	Y3 И 11003	1		
8		Drawing	3K11 044	1		
9		Drawing	АП11-01-01	1		
10		Drawing	АП11-01-02	1		
11		Drawing	Y 803 004	1		
		Total No of sheets		12		
Remarks:-		Y.260 000 Y3.987 010	Sheet 2 & Sheet 3. should not be forwarded			

2

665

9260000CB



- 1). Place stowage of fuses, Ref No.7, in the body, Ref No 2 Close the body with cover, Ref No 1
- 2) Place the tin with fuses in bag, Ref No 3 and put label, Ref No 9, so that inscription is against the walls of bag

4
665

9260.000CB


SNO	SHT	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.84
EDT, CHIC		DIC JAIN		18.12.84
F/M, DC		S. R. NAIL		
LIV, OFFR		A. K. KUNDU		01.01.85

ASSEMBLY DRAWING
FOR STOWAGE OF
SPARE PARTS AND
TOOLS No 1

SHEET	WEIGHT	SCALE
5	0.03	1:1
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

4003.004


4803.000



Drawing No.	Inscription on label	Drawing No.	Inscription on label
4.803.004			
-01	Fuse Cn 15, 30B TY16-522-001-76		
-02			
-03			
-05			

- 1). Make inscription as per table using type 03-8
GOST 3489-10-71
- 2) Using of paper No 2 mark A and B of machine finish
GOST 9095-73 is allowed

4.803.004



SNO	SHY	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.86
EDT, CHKO		D K JAIN		18.12.87
F/M, DC		S.R. NAIR		19.12.87
		A.K. KUNDU		3.01.88

LABEL

Paper No.1 A machine finish
grade-1, GOST 9095-73.

SHEET	WEIGHT	SCALE
0	0.002	1:1
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		



$$\frac{5}{665}$$

STOWAGE OF FUSES

		SHT.NO.	TO NO OF SH
		1	3

93987010C5

перв. примеч.
43 987 010



Designation	Б Article
43.987 010	
-01	
-02	Fuse Cn-15,308
-03	
-04	
-05	
-06	

Place fuses in bag, Ref No1 and the label of this article so that the label inscription is against the walls of bag

7
665

43987010C5

SNO	SHY	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.84
EDT,CHKD		D.K. JAIN		18.12.84
F/M,DC		S.R. NAIR		19.12.84
DIV.OFFR		A.K. KUNDU		30.12.85
		NAME	SIGN	DATE


STOWAGE OF FUSES.
(Assembly drawing)

SHEET	WEIGHT	SCALE
6	102	1:1
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

Восстановлен с подлинника. Верно. 10.4.80г.

34174 33111

93И. 11. 003



ЕКД

9
665

93И 11. 003

SNO	SH	DOC NO	SIGN	DATE
DRAWN		BHUSHAN		17.12.80
EDT,CHKD		D K JAIN		18.12.80
F/M,DC.		S R. NAIR		19.12.80
DIV.OFFR		A.K.KUNDU		30.1.81
		NAME	SIGN	DATE

BAG

Polyethylene film C, O, 1
grade 1, GOST 10354-73.

SHEET	WEIGHT	SCALE.
	50,9g	1:2
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		