Sub: Amendment to Specification No.B.F. 1.10. DT.28/08/82. for the item-Cloth China Sheeting no.1 Gray 36" wide (91.5cm)

Ref:

1) LY/39/NE

DT.17/08/10

2) RK/23/PA

DT.30/11/10

3)0ffice Note No.IO/146/Amend DT.19/01/11

As per letter u/ref.nos.1,2&3 above,Amendment may pl. be made in sub. Spcn. Cl.. No.4.2,Sl.No.3 Charecterstics as follows.

For – Weft pieces per decimetre no. of threads minimum Read –Weft picks per decimetre no. of threads minimum

Hence, It is requested that, Amendment may be incorporated as above in the sub. Spcn. at your end please.

DVO/LY

DVO/WI

DVO/RK

Hangine DVO/10 22/1/11

HUS I IO

J/0/0

Chapter IV

Subject

Textile

Item

Cloth China

sheeting No.1 Grey 36" Wise (91.5 cm)

B.F. Specification No. #.10

Dated : 28.8.82

Supersedes B.F.Specn.No-Nil

Dated : N11

#### SCOPE

This specification prescribes the quality requirements and methods of sampling and tests applicable to cloth china sheeting for purchase from Trade by Ordnance Factory. Blandara.

The material is suitable for use in cleaning Rocket charges.

# GENERAL REQUIREMENTS OF SAMPLING

- The following precautions shall be observed in drawing, preparing, storing and handling of the samples.
- Sampling instruments shall be clean and dry.
- Quantity of each sample drawn will be about 1 metre and two such samples shall be taken, one from either end, from each consignment.
- 2.1 .3 One of the two samples will be used for tests/analysis and other kept in the Ordnance Factory, Bhandara Laboratory for a period of two months or till contract is finalised, whichever is earlier.
- If the first sample is found to fail in specific quality requirements the failing consignment shall be resampled second time and tested.
- 2.5.5 The material in any consignment shall be accepted as confirming to the specification, if the results of testing the corresponding test samples a satisfy the requirements under clause 4.2 below, otherwise the consignment shall be rejected.

### INSPECTION

- General Manager, Ordnance Factory, Bhandara shall be the inspecting authority.
- Mode of Sampling:
  - Tests on samples for quality requirements as stipulated under para 4 below.
  - If the second samples also fails, the whole consignment shall be rejected.

## QUALITY REQUIREMENTS

Description:

The material shall be all cotton, woven with plain

weave, free from flaws, knots and other defects. Yarns shall be evenly made, Selvedges shall be firm and straight. The material shall be in a clean and dry condition. Too much of filling/loading the material shall not be allowed.

4.2 The naterial shall also comply with the requirements given in table I, below, when tested according to the methods prescribed in JSS No. 1250.

### TABE-I

. ;	Sl.No	. Characteristics	Require	ments	Method	of Test
1	1.	Moisture (Regain) at 105 to 110°0 percentage minimum	9.0	ş <b>i</b>	As per (	JSB-1250
÷	,2.	Warpends per decimeter No. of threads minimum				**************************************
	3.	Weft (pieces) per decimeter No. of threads minimum .	220	•		
	4•	Mass <b>graa</b> per sq.metre minimum	108,	2.3	en de la companya de	

- 5. Pocking and Marking
- 5.1 Packing:

Material shall be packed in packages as agreed to by the purchaser and supplier.

5.2 Marking:

All packages in which the naterial is transparted shall be marked as prescribed by law in force from time to time.

(N.S. RAGHAVAN)

GENERAL MANAGER
ORDNANCE FACTORY, BHANDARA

## DISTRIBUTION:

RK, WO, PV, ST, LY, TD, IG

PO, CG, SF, WI, MB

IO & MEB