RUN DATE : 11/02/2021 PAGE No : 1 '

ATERIAL PLANNING SHEET

MP Sheet No : FS1200483 Purchase TRADE

PERIOD OF PROVISIONING : FROM TO

A) Fy : Ordnance Factory Ambajhari Nagpur (127)

B) Input Material (Description / Nomenclature):

CELLULOID DISC TO ARDE DRG.NO. 0901 00 01 01 00 004 00PB (FOR CARTDIGE BODY EMPTY ASSY 0901 00 01 01 00 000 00PB)

C) ITEM CODE: 6732020901

D) A/U : 40/Nos.

VOCAB SECTION :D

USER SECTION: 041/FUZE SHOP.

ITEM TYPE: DIRECT MATERIAL

ITEM CLASS: DRAWING ITEMS/INSTRUMENTS

E) END USE : CARTRIDGE PDO-1 ELECTRIC IGNITERS

CELLULOID DISC DRG NO.0901 00 01 01 00 004 00PB

AHSP : ARDE

INSP RESP : REP.OF GM/OFAJ
Quality Audit & Surveliance :-

MONITORING INSTRUCTIONS FOR VENDOR

- 1. Firm has to take raw material clearance and Firm has to submit raw material sample for testing at OFAJ along with pre-inspection test rep ort from NABL accredited / PSU/ Govt. approved lab for the properties specified in nomenclature, drawing and specifications before starting bulk production.
- 2. Test reports to give reference of OFAJ supply order.
- 3. Firm has to submit proof of raw material purchase and indicate its sufficiency for number of Components to be manufactured from purchased raw material.
- 4. After raw material clearance, Firm has to submit advance sample for clearance before starting bulk production. (Advance sample required from first time supply)
- 5. Components to be manufactured as per the drawing specified in the nomenclature and Firm shall submit inspection report/dimensional report along with supply.
- 6. Firm to take all necessary precautions for proper packaging and sur face protection to avoid corrosion, damage during handling, transporting and storage.
- 7. Component will be subjected to surveillance quality check and performance trial at OFAJ.
- 8. OFAJ team may visit the firm for Process/quality Audit.

ONLINE VETTING OF SIS IS DONE. SO SIGNATURE IS NOT RESQUIRED

HOS/QCIM/QCRM HOS/CDD

HOS/SC

D.O./G.O./STD. CELL