

ВЗ8.825.001

13±0,5

5±0,5

74±1

66±1

1

ЛИСТ УПАКОВОЧНЫЙ
ИЗДЕЛИЕ ТИП _____

КОЛИЧЕСТВО _____ ШТ

ДАТА КОНСЕРВАЦИИ _____

УПАКОВЩИК _____

ОТК _____

ДАТА УПАКОВКИ _____

97±1

105±1

* (1) PACKING LIST
ARTICLE, TYPE _____
QUANTITY _____ PCS
DATE OF PRESERVATION _____
PACKED BY _____
QCD _____
DATE OF PACKING _____

For printing, use type 03-8 ГОСТ 3489.10-71. To print the inscription "packing list", use type 63-16 ГОСТ 3489.7-71

14/02085

APPROVED

CHECKED

CONTROL RATE
OF
INSPECTION
(ICV)

DATA SHEET

WEIGHT SCALE


0.0004 1:1

SHY SHS

Paper No 1, A, Machine
finished, sort 1.

ВЗ8.825.001

AY-530-42



Weld up edges A

13/02085

PROVED

RED

CONTROLLERATE
OF
INSPECTION
(ICV)

AY-530-42

ENVELOPE FOR CERTIFIC-
ATES OR SERVICE LOGS

Polyethylene film C, 0.1,
Sort 1 GOST 10354-73

WEIGHT SCALE

13 g

1:2

SHT

SHTS

Rz max 800 ✓✓

Справ. №	пер. лист	9.653.000
----------	-----------	-----------

80±2

 120 ± 2

Consignee

Destination

Consigner

Dispatch station

Number of packages———Mass

0-03

Y 95 001-'01

for remaining see y.95.001

Consignee

Airport of destination

Consigner

Dispatch airport

Number of packages _____ Mass _____

1. Moisture in the plywood should not exceed 15% absolute unit.

2. Marking stamping point as per Ty-6-15-459-70 type 5 as per H0 010.007.

5
1673

4.95.001

SHEET	WEIGHT	SCALE.
-------	--------	--------

NAME PLATE

Б 0,022 251

TOTAL SHEETS

Plywood $\phi 5A$ Grade $\frac{AB}{B}$


ORDNANCE FACTORY
PROJECT
HYDERABAD

GOST 3916-69

SNO	SHY	DOC NO	SIGN	DATE
DRAWN		N Yesudas		11/12/84
EDT,CHKD		D K SAIN	<i>[Signature]</i>	12-12-84
F/M,DC.		S R Nair	<i>[Signature]</i>	13-12-84
DIV.OFFR		T.K. RANDEE	<i>[Signature]</i>	17-12-84
		NAME	SIGN	DATE

9460.002

$R_{2max} = 800 \text{ V}$

[illegible]

1 *Dimension is given for reference

7
I-673

y.460.002

SNO	SHT	DOC NO	SIGN	DATE
DRAWN		N Yesudas		11.12.8
EDT/CHKD		D IS JAIN		12.12
F/M, DC.		S R Nair		13-12-8
DIV.OFFR		T K BANERJEE		17-12-8
		NAME	SIGN	DATE


DISTANCE PIECE

SHEET		WEIGHT		SCALE	
	6	Self table		—	
		TOTAL SHEETS			
ORDNANCE FACTORY PROJECT HYDERABAD					

Fibre wood plate mark
T-350 GOST 4598-74

700.1096

R_Z max 800/ (✓)



1. Moisture of plywood should not exceed 15%, absolute
2. *Dimension is given for reference
3. Alternate material is fibre wood plate mark T-350 thickness 32 GOST 4598-74.

8
I-673

700.1096

Y-607-002

SNO	SHY	DOC NO	SIGN	DATE
DRAWN	N	Yesudas		11.12.84
EDT, CHIC	D K	JAIN		12.12.84
F/M, DC	S R	Nair		13.12.84
DIV, OFFR	T K	BANERJEE		13.12.84
	NAME	SIGN	DATE	


PARTITION

Plywood mark ϕ 5A,
variety $\frac{AB}{B}$ GOST 3916-69

SHEET	WEIGHT	SCALE
5	000000 M ³	1:5
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

5607.003

✓d3(✓)
R₂max 800
✓(✓)



- 1, Moisture of plywood should not exceed 15%, absolute.
- 2 *Dimension is given for reference.
- 3 Alternate material is fibré wood plate mark II-350, thickness 32 GOST 4598-74

9
I-673

5607.003

SNO	SHT	DOC NO	SIGN	DATE
DRAWN		N Yesudas		11/12/84
EDT, CHKD		K. JAIN		12/12/84
FM, DC		S.R. Nair		13/12/84
DM OFFR		T.K. BAKER		17/12/84
		NAME	SIGN	DATE

PARTITION

Plywood mark Φ 5A, Grade AB
GOST 3916-69

SHEET	WEIGHT	SCALE
5	0.00008 M ³	1:5
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		

3
I-673


y3.607.000	
PACKING CASE (PH-10 SPARE PARTS AND TOOLS NO 2)	SHT.NO.
	TO NO OF SH
ORDNANCE FACTORY PROJECT HYDERABAD	

ALBUM No 131

TECHNICAL PAPERS FOR ARTICLES
"84/0848711-03-rБ-40007"

MAIN PRODUCTION DRAWING

Sheets 9



(PH-10. Spare parts & tools No.2)

PACKING CASE

y3 607-000


CONTENTS : OF ALBUM No. 131

CONVENTIONAL INDEX : B4/0848711-03-rb-40007"


Sl. No.	DRAWINGS ASSEMBLIES ITEM Nos.	DESCRIPTION OF DOCUMENTS	DRAWING Nos. (PROCESS CHART	Qty of shts.	LATEST AMENDMENT NO.	REMARKS
1	2	3	4	5	6	7
1	Album of drawing of packing case of PH-10-3 SPTA No.2 y3 617 000	Title sheet	y3.607.000	1		
2		Parts list	y3 607 000	1		
3		Assembly drawing	y3.607.000cb	1		
4		Drawing	y.95 001	1		
5		Drawing	y 530 -42	1		
6		Drawing	y 460 002	1		
7		Drawing	y 607.002	1		
8		Drawing	y 607.003	1		
9		Drawing	B08 825.001	1		
		Total number of sheets		9		

1

I-673



Cover is not shown



- 1 Put the partitions, Ref Nos 7,8, in the box, Ref No 1, in order to form the compartments
- 2 Before packing in the box wrap two layers of paper, Ref.No.14, and one layer of paper, Ref No 13, around the article.
- 3 Do not store the articles in two layers. Place spacer, Ref No 5, in each layer
- 4 Put table, Ref.No.3, in the envelope Ref.No.4. Put the envelope with documents in the box.
- 5, Close the box with cover Nail cover and band with nails, Ref No 10
- 6 On one of the box end walls, nail name plate Ref No.6 with nail Ref No. 11.

93.607.000C5

SHEET	DOC NO	SIGN	DATE
DRAWN	N.Yesudas		11/12/84
EDT,CHKD	S.K. JAIN		12/12/84
FM,DC	S.R.Nair		13/12/84
DIV.OFFR	T.K. GANESH		11/12/84
NAME	SIGN	DATE	

PACKING CASE
PH-103Un No 2
ASSEMBLY DRAWING

SHEET	WEIGHT	SCALE
5	16	1:2
TOTAL SHEETS		
ORDNANCE FACTORY PROJECT HYDERABAD		