

ANNEXURE A

**LIST OF ESSENTIAL MACHINES FOR MANUFACTURING OF THE
SUBJECT ASSEMBLY**

1. LATHE (OR) CNC TURNING CENTRE
2. MILLING MACHINE AND CNC VMC
3. HEAT TREATMENT
4. ZINC PLATING BATH