

**Plant & Machinery and Lab Equipment requirement for Cloth CEE Heavy 72 cm
(C.N.H2/8305)**

SL. NO	ITEM	END USE	MANUFACTURING PLANT & MACHINERY		TEST EQUIPMENTS		REMARKS
			ESSENTIAL	DESIRABLE	ESSENTIAL	DESIRABLE	
01.	Cloth CEE Heavy 72 cm (C.N.H2/8305)	• Packing	Suitable Looms for Jute Weaving	Jute Spinning & Processing	Conditioning Chamber		
					Measuring Scale		
					Pick Glass		
					Weighing Balance		
					Tensile Testing Machine		