

PRE-QUALIFICATION CRITERIA FOR PUBLISHING IN ADVANCE VENDOR REGISTRATION(AVR-8)
Ref: GM Sanction ltr No. EFA/MM/OTE/Make-II/PQC dtd 12.03.2021

Item details

LF No.	6211008000
Nomenclature	ASSY EXHAUST MANIFOLD
Drawing Number	SB 418-00-6

Mandatory Requirements

1. The firm should have In-house facility to manufacture complete Exhaust Manifold and its accessories (Both LH and RH)
2. Should have reliable source for Steel Sheets as per drawing
3. Should have facility or tie-up with press tool manufacturer
4. In-house facility for welding, machining and grinding with relevant fixtures.
5. Should have pressure testing facility to ensure air-tightness as per specification.
6. Should have complete inspection facility including checking of surface flatness and roughness.
7. Firm should have traceability of all its production & supplies to facilitate proper investigation if a product lot is found defective
8. Firm should have tie-up with leading metallizing service providers specialized in Aluminium oxide mixtures.
9. Firm should practice modern methods in preservation of raw material, transportation and preservation of finished goods and packing and forwarding of stores to EFA to avoid any damage or rusting to End Product

Optional Requirement

2. Firm may be ISO 9000, 14000 certified with valid certificate



CA Jithin,
JWM/EAS-II
Member



K. Ramesh Kumar
JWM(SG)/QC
Member



Rahul Sharma
WM/QC
Member




Rohit Panchal
WM/EAS-II
Chairman

Approved/ ~~Not approved~~

Approved/ ~~Not approved~~



AGM/MM 2/6/21



AGM/QC 19/6/21