

ANNEXURE -C

LIST OF ESSENTIAL PLANT & MACHINERY REQUIRED

SL.NO	NOMENCLATURE	QUANTITY	PLANT & MACHINERY REUIRED
01.	SUPPLY OF EPD FUZE PCBS(PCB-I& PCB-II)ASSEMBLED WITH ALL ELECTRONIC COMPONENTS AS PER BILL OF MATERIAL AND GERBER FILES ENCLOSED AS ANNEXURE-'A' AND ANNEXURE-'B' RESPECTIVELY.	500 Nos	1.Precision Stencil Printer 2.Pick & place machine 3.Reflow oven 4.Wave soldering machine 5.CAD Software 6.Solder Paste Dispensing machine 7.Thermal Cycling Chamber 8.Ultrasonic cleaning machine 9Automatic optical inspection system 10.DC regulated power supply. 11.Digital multimeter.