

CONTEST OF ALBUM No. 59

CONVENTIONAL INDEX : "84/0848711-03-ГБ-40007"

Sl. No.	DRAWINGS ASSEMBLIES ITEM Nos.	DESCRIPTION OF DOCUMENTS	DRAWING Nos. (PROCESS CHART)	Qty of shfs.	LATEST AMENDMENT NO.	REMARKS
1	2	3	4	5	6	7
1	Album drawings of wings of	Title sheet	PM6-1C.000	1	-	
2	Traction relay PM6-1C	Specification	PM6-1C.000	3		
3	PM6-1C.000	Assembly drawing.	Sheet 1 Sheet 2 Sheet 3			
4		Out. linedrawing.	PM6-1C.000CB PM6-1C.000Г4	1 1		
5		List of specifications	PM6-1C.000BC	1		
6		List of connected documents	(PM6-1C.000B)A Sheet 1 Sheet 2 Sheet 3	3		
7		Specification	PM6-1C.020 Sheet 1 Sheet 2	2		
8		Assembly drawing	PM6-1C.020CB	1		
9		Specification	PM6-1C.030	1		
10		Assembly drawing,	PM6-1C.030CB	1		
11		Specification	PM6-1C.040	1		
12		Assembly drawing.	PM6-1C.040CB	1		
13		Specification	PM6-1C.050	1		

1
D-602

CONTEST OF ALBUM No. 59

CONVENTIONAL INDEX : "84/0848711-03-ГБ-40007"

Sl. No.	DRAWINGS ASSEMBLIES ITEM Nos.	DESCRIPTION OF DOCUMENTS	DRAWING Nos. (PROCESS CHART)	Qty of shts.	LATEST AMENDMENT NO.	REMARKS
1	2	3	4	5	6	7
14		Assembly drawing.	PM6-1C.050CB	1		
15		Specification	ПП-511-79	1		
16		Assembly drawing.	ПП-511-79CB	1		
17		Drawing,	PM6-1C.003	1		
18		Drawing	ПП1.003.	1		
19		Drawing	PM6-1C.004	1		
20		Drawing	PM6-1C.005	1		
21		Drawing.	PM6-1C.006	1		
22		Drawing,	PM6-1C.007	1		
23		Drawing	PM6-1C.008	1		
24		Drawing	PM6-1C.009.	1		
25		Drawing	PM6-1C.011	1		
26		Drawing	X-1012	1		
27		Drawing	CA-18-66	1		
28		Drawing	X-4001	1		
29		Drawing	X3-9660	1		
30		Drawing	X1-9895	1		
31		Drawing	X5-9960	1		
32		Drawing	X2-102-14	1		
33		Drawing	X2-10630	1		
34		Drawing	X5-11052	1		
35		Drawing	ПП-161-68	1		
36		Drawing	X1-490-92	1		
37		Drawing	ПП511-67	1		
38		Drawing	ПП-511-80	1		
		Total sheets.		43.		

FORMAT	ZONE	REF. NO.	DESIGNATION.	DESCRIPTION.	QTY	REMARKS
				Documents.		
22			PM6-1C.000CB	Assembly drawing.		
22			PM6-1C.000CD	Out line drawing.		
12			PM6-1C.000BC	Specifications list.		
11			PM6-1C.000BA	list of reference documents		
11			PM6-1C.000TY	Specifications		Seperate album.
32			PM6-1C.000PC-Γ	Certificate to relay batches.		Ditto,

4/0.60%

S.NO.					PM6-1C.000.				
SHT									
DOC.NO.									
SIGN.									
DATE					11/12				
DRAWN BY					S.GOPAL				
CHECKED					AK DOBRY				
F/M.DC.					S.R.NAIR.				
DIV.OFFR.					A.K.KUNDU				
NAME.					SIGN.				
					DATE				

SHT.NO.		TO.NO.OF.SHT	
1		3	

TRACTION RELAY

FORMAT	ZONE.	REF. NO.	DESIGNATION.	DESCRIPTION.	QTY	REMARKS
				Standard items.		
		7		Ring T930-20-2 GOST11025-78	1	X5-11062 Maximum quantity 2 pieces.
		8		Washer 465 T 06 GOST6402-70	4	X-1012
		9		Washer 565 T 06 GOST6402-70	2	X-4001.
				Material.		
		11		Wire KO 0.8 GOST792-67.	0.2M	
11			y -728-30.	Sets: Traction relay. PM6-1C Packaging.	1	Separate album.

6
D.602

PM6-1C.000

S.NO	SHT	DOC.NO.	SIGN.	DATE
		S Gopal		11/17
		A K DUBEY	<i>AK</i>	3.12.85
		S.R.NAIR.	<i>SR</i>	14.12.85
		A.K.KUNDU	<i>AK</i>	3.01.85
		NAME.	SIGN.	DATE

TRACTION RELAY

Easy2Convert
www.easy2convert.com

SHT.NO. TO.NO.OF.SHT

3

3

5-1/3

3-5-A4

FORMAT	ZONE.	REF. NO.	DESIGNATION.	DESCRIPTION.	QTY	REMARKS
				Technical papers.		
12			PM6-1C.030CB	Assembly drawing.		
				Assembly units.		
11	1		PΠ-511-79	Casing with cover: Plate.	1	
				Parts.		
11	2		Pm6-1c.004	Core,	1	
11	3		X3-9660.	Washer.	1	

PM6-1C.030

15
D-602

S.NO	SHT	DOC.NO.	SIGN.	DATE
		S.Gopal		11/12
		A.K. KUNDU		13/12
		S.R.NAIR.		14/12/97
		A.K. KUNDU		20/12/98
		NAME.	SIGN.	DATE

CORE CASE.

SHT.NO.	TO.NO.OF.SH
	1
	1-5-1

