

RUN DATE : 11/02/2021

PAGE No : 1

ATERIAL PLANNING SHEET

FM/CMC/14

Issue No:01

Issue Date:01/10/2009

MP Sheet No

: FS1200481

Purchase TRADE

PERIOD OF PROVISIONING : FROM

TO

A) Fy : Ordnance Factory Ambajhari Nagpur (127)

B) Input Material (Description / Nomenclature):

TRANSIT CAP TO ARDE DRG.NO. 0901 00 02 01 00 005 00PB (FOR

SQUIB HOUSING ASSY (EMPTY) TO DRG.NO. 0901 00 00 02 01 000
00PB)

C) ITEM CODE:6732020904

D) A/U :40/Nos.

VOCAB SECTION :D

USER SECTION : 041/FUZE SHOP.

ITEM TYPE: DIRECT MATERIAL

ITEM CLASS: DRAWING ITEMS/INSTRUMENTS

E) END USE :CARTRIDGE PDO-1 ELECTRIC IGNITERS

TRANSIT CAP TO DRG NO.0901 00 02 01 00 005 00PB

AHSP : ARDE

INSP RESP : REP.OF GM/OFAJ

Quality Audit & Surveliance :-

MONITORING INSTRUCTIONS FOR VENDOR

1. Firm has to take raw material clearance and Firm has to submit raw material sample for testing at OFAJ along with pre-inspection test report from NABL accredited / PSU/ Govt. approved lab for the properties specified in nomenclature, drawing and specifications before starting bulk production.
2. Test reports to give reference of OFAJ supply order.
3. Firm has to submit proof of raw material purchase and indicate its sufficiency for number of Components to be manufactured from purchased raw material.
4. After raw material clearance, Firm has to submit advance sample for clearance before starting bulk production. (Advance sample required from first time supply)
5. Components to be manufactured as per the drawing specified in the nomenclature and Firm shall submit inspection report/dimensional report along with supply.
6. Firm to take all necessary precautions for proper packaging and surface protection to avoid corrosion, damage during handling, transporting and storage.
7. Component will be subjected to surveillance quality check and performance trial at OFAJ.
8. OFAJ team may visit the firm for Process/quality Audit.

ONLINE VETTING OF SIS IS DONE. SO SIGNATURE IS NOT RESQUIRED

HOS/QCIM/QCRM

HOS/CDD

HOS/SC

D.O./G.O./STD. CELL
