

Manufacturing Technology :

1. Mixer
2. Sieve

Inspection Technology:

Following test as per Drg./QAP/Spec

1. Volatile matter,% by mass
2. Drying time minutes
3. Adhesion test
4. Kinematic viscosity