

Sl.No.	Component/Raw material	Manufacturing technology	Testing/Inspection Facility
1	Extractor JVPC 5.56MM thorough MIM route DRG No.0204-03-04-00- 05-002-00DA	MIM Route	1-Chemical and mechanical properties as per std. given drawing. 2- Dimensional inspection, for all dimensions given in the drawing a other parameter which are mentioned in relevant drawing