

No-107/058.02/IMS/25
Date: 17-06-2022

SUB:- IDENTIFICATION OF MANUFACTURING TECHNOLOGY & INSPECTION / TESTING FACILITY.

The multi functional team has discussed about the manufacturing technology & inspection / testing facility of following items and came in decision that the following manufacturing technology & inspection / testing facility are required to manufacture the item.

SLNo.	Item	Manufacturing Technology & Inspection / Testing Facility
1	BRASS ROD 38.1MM $\pm$ 0.1MM DIA BS-2874.1986 CZ-122 PB3-IN ⁴ M" CONDITION	(i) Melting Furnace (ii) Rolling Machine