No-107/058/02/IMS/25/4 Date: 14-02-2023

SUB:- IDENTIFICATION OF MANUFACTURING TECHNOLOGY & INSPECTION / TESTING FACILITY.

The multi functional team has discussed about the manufacturing technology & inspection / testing facility of following items and came in decision that the following manufacturing technology & inspection / testing facility are required to manufacture the item.

	2	<u> </u>	Sl.No.
Ring to Drg. No. (4-025998-076), (1 Set = Consists of Axle Pin 6 Nos, Tracer Nut 01 No, Semi Ring 2 Nos) for Stabilizer of 125 mm (v) Surface Treatment (as per draw.)	Set of Tracer Nut to (Drg. No.4-025998-036), (i) CNC Turning facility (Core area),	Rivet (Stabilizer Assy) to GSF SK. No. M- (i) Power Press facility (Core area),	Item
 (ii) Pressing facility (Core area), (iii) Drilling facility (Core area), (iv) Milling facility (Core area), (v) Surface Treatment (as per drawing) facility. 	(i) CNC Turning facility (Core area),	(i) Power Press facility (Core area),	Manufacturing Tall 1 at