

No-107/058/02/IMS/25
Date: 21 -06-2023

SUB:- IDENTIFICATION OF MANUFACTURING TECHNOLOGY & INSPECTION / TESTING FACILITY.

The multi functional team has discussed about the manufacturing technology & inspection / testing facility of following items and came in decision that the following manufacturing technology & inspection / testing facility are required to manufacture the item.

Sl.No.	Item	Manufacturing Technology & Inspection / Testing Facility
1	Head Automatic cocking rammer Assy. To Drg. No.2007475 in F/c (Item Code: 7110507475)	(i) CNC Turning facility (Core area) (ii) CNC Milling (or VMC) with 5 Axis facility (Core area) (iii) Boring facility (Core area) (iv) Drilling facility (Core area) (v) Spring Coiling facility (vi) Heat Treatment facility (vii) Surface Treatment facility